





# Emerson Park

## Building Inspection Recommendation

-  No Inspection Needed  
Structure is sound and well maintained.
-  Inspect for Rehab Potential  
Structure is sound, but major material replacement is required.
-  Inspect for Demolition  
Structure is unsound and should be torn down.
-  No Building

*Emerson Park Neighborhood Revitalization Plan*

 **East St. Louis Action Research Project**

University of Illinois at Urbana-Champaign

0 500 1000 1500 Feet



East St. Louis Action Research Project  
111 Temple Hoyne Buell Hall  
611 East Lorado Taft Dr, Champaign, IL 61820  
URL: <http://www.imlab.uiuc.edu/eslarp>  
Printed: May 1999

