

Emerson Park

Building Condition

-  **Good**
No obvious maintenance or repairs needed
-  **Fair**
Minor maintenance or cosmetic repairs needed
-  **Deteriorated**
Structural damage; material replacement required, but building is salvageable
-  **Dilapidated**
Missing materials and structural damage beyond repair
-  **No Building**

Emerson Park Neighborhood Revitalization Plan

 **East St. Louis Action Research Project**

University of Illinois at Urbana-Champaign

0 500 1000 1500 Feet



East St. Louis Action Research Project
111 Temple Hoyne Buell Hall
611 East Lorado Taft Dr, Champaign, IL 61820
URL: <http://www.imlab.uiuc.edu/eslarp>
Printed: May 1999

