


Emerson Park

Sidewalk Conditions



-  **Good**
Clean, level and no cracks or weeds.
-  **Fair**
Few small cracks and weeds.
-  **Poor**
Large cracks, a few missing sections and weeds.
-  **Deteriorated**
Many missing sections, overgrown with weeds.
-  **Destroyed or No Sidewalk**
No sidewalk or surface is completely destroyed.

Emerson Park Neighborhood Revitalization Plan

 **East St. Louis Action Research Project**

University of Illinois at Urbana-Champaign

0 500 1000 1500 Feet



East St. Louis Action Research Project
 111 Temple Hoyne Buell Hall
 611 East Lorado Taft Dr, Champaign, IL 61820
 URL: <http://www.imlab.uiuc.edu/eslarp>
 Printed: May 1999